

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




FIGURE 1 SCANNER SYSTEM BLOCK DIAGRAM.





FIGURE 2. LAYOUT, SEARCH AND RESCUE SCANNER 2 AXIS STABILIZED OPTICAL HEAD



NOTES: 1. ALL DIMENSIONS ARE IN FEET ON
LEVEL GROUND FOR 10,000 FT.
AIRCRAFT ALTITUDE
2. SCAN PATHS ARE SHOWN WITH EXAGGERATED
STABLE PLATFORM ROLL OSCILLATION FOR EASE OF PRESENTATION

FIGURE 3 - PROJECTION OF CROSS-TRACK SCAN ON LEVEL GROUND FOR
1,860 FT. SCANNER ALTITUDE (NO DETECTION FOLDOVER CORRECTION)




FIGURE 4 LAYOUT OF HEAD-MOUNTED CORNER CUBE ASSEMBLY




FIGURE 5 OPTICAL HEAD LAYOUT MOUNTED IN F-16 TRAVEL POD SHOWING WINDOW REFLECTIONS ARE NOT SEEN BY RECEIVERS





FIGURE 6 F-16 WITH LUGGAGE POD FOR SCANNER, SHOWN (RIGHTMOST)

FIGURE 7 LASER RAY PATHS IN SCANNER (PITCH STABILIZATION MIRROR NOT SHOWN)






FIGURE 8




FIGURE 9 COMBAT SEARCH AND RESCUE SCANNER MODIFIED INTO IRST SCANNER